

5 September 2025

Document Ref: BAL2025-0092AA | Rev 0

Kate Barry
45 River Street
Ballina, NSW

Attention: Kate L Barry

Dear Kate,

RE: PROPOSED POOL
13/174 FOWLERS LANE, BANGALOW

1.0 INTRODUCTION

CMW Geosciences (CMW) was engaged by Kate Barry to carry out a geotechnical investigation for the site located at 13/174 Fowlers Lane, Bangalow. This is for a pool proposed at the site. (refer to Figure 1).

The purpose of this report is to summarise the investigation findings in the 2 hand augers HA01 and HA02 with associated Dynamic Cone Penetrometer (DCP) and shear vane strength testing to establish the soil strength and identify the allowable bearing capacity of the subgrade and classify the site to assist with pool foundation.

The scope of work and associated terms and conditions of our engagement were detailed in our services proposal email referenced 'Geo Tech Report required for new pool in Bangalow', dated 13/08/2025.




Figure 1: Site Plan with Hand Auger locations overlain. (Courtesy of Kate Barry)

2.0 SITE DESCRIPTION

Figure 2 and Figure 3 Indicate the location of the proposed pool is on gently sloped ground surface falling away from the residential structure towards the football field at around 20 degrees. It is understood 'cut and fill' earthworks have occurred to different levels across the site.



Figure 2: Location of the proposed pool



Figure 3: Indication of angle of slope

3.0 GEOLOGICAL SETTING

The published geological map for the area presented in Figure 4 shows the site is underlain by the Lismore Basalt. Details of the lithology in the area are provided in Table 1.

Table 1: Summary of Geological Units

Lithology	Reference	Description
Lismore Basalt (27.82 – 20.44 Ma)	NMlal	Predominantly tholeiitic with occasional alkaline types of formations.



Figure 4: Geological Map

4.0 FIELD INVESTIGATION

4.1 Scope of Field Investigation

All fieldwork was coordinated by CMW and carried out in general accordance with AS1726 (2017), Geotechnical Site Investigation, on the 18/08/2025. The fieldwork completed comprised of:

- A walkover survey of the site to assess the general landform, conditions and adjacent infrastructure.
- Two hand augers, denoted as HA01 and HA02 were both advanced to 2.1m with associated shear vane strength testing.
- Two DCP (Dynamic Cone Penetration) tests were advanced adjacent to each hand auger location to depths of 2.9m.
- Two samples collected from HA01 location at a depth of 1.9m were tested for Atterberg Limits and soil aggressivity tests.

Borehole logs, DCP results, and laboratory test results are provided in Appendix A and Appendix B.

4.2 Subsurface Strata

The ground conditions encountered and inferred from the investigation across the proposed pool area can be generalised according to the following subsurface sequence:

- FILL comprised stiff to very stiff Clayey SILT to Sandy CLAY, low to medium plasticity with gravel, dark brown to brown coloured to a depth of 1.9m at hand auger locations.
- Natural soil comprises very stiff silty CLAY, inferred as residual Lismore Basalt, medium plasticity, mostly red coloured.

4.3 Groundwater

No groundwater was encountered in the hand augers.

5.0 LABORATORY TEST RESULTS

Laboratory testing was carried out in accordance with the current edition of AS 1289 (where applicable).

The laboratory testing was performed by Construction Sciences and Environmental Analysis Laboratory (EAL) which are NATA accredited testing authorities.

Results of the laboratory testing are presented below.

Table 2: Summary of Laboratory Test Results

Test ID	Depth (mBGL)		LL %	PL %	PI %	LS %	Sulphate (mg/kg)	Chloride (mg/kg)	Resistivity in soil (ohm.cm)	pH (-)	Exposure Classification	
	From	To									Concrete	Steel
HA01	1.9	2.1	57	40	17	14.0	30	42.1	18500	5.47	Moderate	Non-aggressive

6.0 GEOTECHNICAL FINDINGS

6.1 Site Classification

The classification of foundation soil reactivity indicates the propensity of the ground surface to move with 'normal' seasonal moisture variation. The magnitude of moisture related seasonal ground movements should be considered in design of structures. The site classification is based on procedures presented in AS 2870:2011 Residential Slabs and Footings, the typical soil profiles revealed at the test locations and the results of laboratory testing.

The site has been classified as a "Class P" in accordance with AS2870-2011. The Class P classification is based on the presence of uncontrolled fill at the site to a depth of 1.9m. Before founding a suitable footing type, unsuitable materials (fill, topsoil) may need to be removed and, if necessary, be replaced with engineered fill in accordance with AS 3798 'Guidelines on earthworks for commercial and residential developments. If placement of fill is required, provided uncontrolled fill has been removed, the site may be reclassified and given an alternative classification if assessed in accordance with general engineering principles.

The site classification is for the site in its current state and is based on the information obtained from the bores, the results of laboratory testing and CWM Geosciences experience with similar subsurface conditions in the area. In the event that the conditions encountered at the site are different to those presented in this report, it is recommended that advice be obtained from this office.

It should be noted that this classification is dependent on proper site maintenance, which should be carried out in accordance with AS 2870-2011 and the attached guidance (CSIRO, 2012), titled “Foundation Maintenance and Footing Performance: A Homeowners Guide”, a copy of which is included in Appendix C.

6.2 Allowable Bearing Capacity

On the basis of DCP test results at the foundation level of the pool (minimum 1.7m below ground level), an allowable bearing pressure of 100kPa is anticipated to be available at the founding level, provided uncontrolled fill is removed and replaced with engineered fill in accordance with AS 3798, as required.

Further works required as part of the detailed design would include the following:

While a minimum allowable bearing pressure of 100kPa is considered suitable, considerations should be given to potential differential movements due to potential non-uniform ground conditions across the foundation area and potential for moisture related seasonal ground movements, subject to extents and thicknesses of any controlled fill placed as part of the works.

6.3 Excavation Conditions

Excavation recommendations based on the investigations are summarised as follows:

- Temporary excavations where people are expected to enter, or where the trench exceeds 1.5m depth must be appropriately shored or battered back at slopes no greater than 1V (Vertical): 2.5H (Horizontal) in accordance with NSW Codes of Practice; and
- Excavation up to a depth of around 1.7m are expected to be readily undertaken using conventional plant such as a 20T excavator.

7.0 CLOSURE

This report has been prepared for use by Kate Barry in relation to the 13/174 Fowlers Lane, Bangalow project in accordance with the scope, proposed uses and limitations described in the report. Should you have further questions relating to the use of your report please do not hesitate to contact us.

Where a party other than Kate Barry seeks to rely upon or otherwise use this report, the consent of CMW should be sought prior to any such use. CMW can then advise whether the report and its contents are suitable for the intended use by the other party.

For and on behalf of CMW Geosciences

Prepared by:



Tom Strawbridge
Engineering Geologist

Reviewed and authorised by:



Thomas Platel
Principal Geotechnical Engineer

Distribution: 1 electronic copy to Kate Barry via email
Original held at CMW Geosciences

Attachments: Appendix A - Borehole logs
Appendix B - Laboratory Test Reports
Appendix C – CSIRO Sheet BTF 18



APPENDIX A

Borehole logs

Client: Kate L Barry
Project: New Pool, Fowlers Lane, Bangalow
Location: 13/174 Fowlers Lane, Bangalow
Project ID: BAL2025-0092
Date: 18/08/2025







Plant used: Hand Auger

Sheet 1 of 1

Logged by: TS Position: E.550657m N.6831015m
Checked by: HT Elevation:

Plant used: Hand Auger
Contractor: CMW Geosciences

Well	Groundwater	Samples & Insitu Tests		RL (m)	Depth (m)	Graphic Log	Material Description Soil Type, Plasticity or Particle Characteristics, Colour, Secondary and Minor Components	Moisture Condition	Consistency/ Relative Density	Dynamic Cone Penetrometer (Blows/100mm)			Structure & other observations
		Depth	Type & Results							5	10	15	
		0.90	HV=135kPa HVR=45kPa		1		OL: Organic SILT: low plasticity dark grey (TOPSOIL)	≈PL	St to VSt				
							MH: Clayey SILT: low plasticity, brown, mottled grey, with Gravel, fine grained, angular (Fill)						
										CL: Silty CLAY: low plasticity, dark brown, mottled white and brown, with gravel, fine grained, angular (Fill)			
													
													
													
													
													
													
													
					3								
DCP/PSP Equipment Ref.: DCP01						In Situ Vane Ref.: #4062		Pocket Penetrometer Equipment Ref.:					
Termination Reason: Hand Auger Refusal													
Remarks: Soil consistency based on Shear Vane and DCP values and observations.. Groundwater was not observed.													
This report must be read in conjunction with accompanying notes and abbreviations.													

BOREHOLE LOG - HA02

Client: Kate L Barry
Project: New Pool, Fowlers Lane, Bangalow
Location: 13/174 Fowlers Lane, Bangalow
Project ID: BAL2025-0092
Date: 18/08/2025

Logged by: TS
Checked by: HT

Position: E.550655m N.6830996m
Elevation:

Plant used: Hand Auger
Contractor: CMW Geosciences

Well	Groundwater	Samples & Insitu Tests		RL (m)	Depth (m)	Graphic Log	Material Description Soil Type, Plasticity or Particle Characteristics, Colour, Secondary and Minor Components	Moisture Condition	Consistency/ Relative Density	Dynamic Cone Penetrometer (Blows/100mm)			Structure & other observations
		Depth	Type & Results							5	10	15	
							OL: Organic SILT: low plasticity, dark brown (TOPSOIL)			2			
							MH: Clayey SILT: low plasticity, brown, mottled grey and brown, with gravel, medium to coarse grained, angular, trace sand, fine grained (Fill)			2			
										3			
										5			
								<PL	St to VSt	5			
										12			
										5			
										7			
							CL: Sandy CLAY: low plasticity, dark brown, Sand, fine grained, with gravel, fine to medium grained, sub-angular (Fill)			4			
					1			≈PL		5			
										7			
							MH: Clayey SILT: low plasticity, brown, with gravel, fine to medium grained, sub-angular to sub-rounded (Fill)			9			
										7			
										8			
									VSt	10			
								≈PL		5			
										6			
										7			
										6			
					2		CL: Silty CLAY: low plasticity, brown to red (Residual)			6			
										7			
							Borehole terminated at 2.10 m			6			
										5			
										5			
										6			
										7			
										7			
										6			
										7			
					3								

DCP/PSP Equipment Ref.: DCP01In Situ Vane Ref.:Pocket Penetrometer Equipment Ref.:Termination Reason: Hand Auger RefusalRemarks: Soil consistency based on Shear Vane and DCP values and observations. Groundwater was not observed.

This report must be read in conjunction with accompanying notes and abbreviations.

APPENDIX B

Laboratory Test Reports

ATTERBERG LIMITS REPORT

Client:	CMW Geosciences - Ballina	Report Number:	22373/R/25-3401-2
Client Address:	313 River St, Ballina	Project Number:	22373/P/333
Project:	BAL2025-0092 Kate Barry	Lot Number:	N/A
Location:	Northern Rivers	Internal Test Request:	22373/T/25-1296
Component:	Material Assessment	Client Reference/s:	BAL2025-0092
Area Description:	New Pool Development	Report Date / Page:	29/08/2025 Page 1 of 1

Test Procedures:	AS1289.3.1.2, AS 1289.3.3.1, AS1289.3.2.1, AS1289.3.4.1, AS1289.2.1.1		
Sample Number	22373/S/25-6172	Sample Location	
Sampling Method	Tested As Received	Location	HA01
Date Sampled	19/08/2025		1.9m
Sampled By	Client Supplied		2.1m
Date Tested	21/08/2025		N/A
Drying / Prep Method	Oven Dried / Dry Sieved	Material Source	Not Supplied
LL Water Type	Potable	Material Type	Not Supplied (Not Supplied)
LL Device Type	Cassagrande	Specification	Not Supplied
Client Reference	BAL2025-0092	Prep Mat > 53mm (%)	-
Material Description	sandy CLAY		

Atterberg Limit	Specification Minimum	Test Result	Specification Maximum
Liquid Limit (%)		57	
Plastic Limit (%)		40	
Plasticity Index (%)		17	
Linear Shrinkage (%)		14.0	
Linear Shrinkage Observations:	-		

Remarks	Re-Issued Report Replaces Report No 22373/R/25-3401-1 (reason: Amended Client Ref)., Results apply to the sample/s as received.,
---------	--

 Accredited for compliance with ISO/IEC 17025 – Testing Accreditation Number: 1986 Corporate Site Number: 22373		 Approved Signatory: Timothy Sheahan Form ID: W11bRep Rev 2
---	--	---

Soil - Certificate of Analysis - E25-00-9174

Client:	CMW Geosciences Pty Ltd	Laboratory:	Environmental Analysis Laboratory
Contact:	Tom Strawbridge	Contact:	EAL Customer Service Team
Address:	313 River Street, Ballina, NSW 2478, Australia	Address:	Military Road, East Lismore NSW 2480, Australia
Telephone:	0480 733 820	Telephone:	(02) 6620 3678
Email:	tom.strawbridge@cmwgeo.com	Email:	eal@scu.edu.au

Customer reference:	PO BAL140555 - BAL2025-0092	Request ID:	EAL/E25-00-9174
Number of samples:	1	Report ID:	E25-00-9174_EALP1_1
Date samples received:	21 August 2025	Issue date:	01 September 2025

Authorised by:	Nadia Toppler
Position:	Senior Manager - Laboratory Operations



Comments: EAL is a NATA accredited laboratory (14960), accredited for compliance with ISO/IEC 17025 - Testing.

Certificate of Analysis

Request ID: EAL/E25-00-9174 Report ID: E25-00-9174_EALP1_1 Issue date: 01 September 2025

Client Sample ID:				HA01
Sample Depth:				1.9-2.1
EAL Sample ID:				E25-00-9174-0001
Parameter	Unit	Method Reference	LOR	---
Moisture Content	%	Inhouse S2 (105)	<0.1	31.1
Texture (Coarse/Medium/Fine)	---	** Inhouse S90	---	Medium
pH (H ₂ O)	units	Rayment & Lyons 2011 - 4A1	---	5.47
Electrical Conductivity	dS/m	Rayment & Lyons 2011 - 3A1	<0.005	0.054
Resistivity	ohm.mm	** Calculation	---	185000
Resistivity	ohm.cm	** Calculation	---	18500
Chloride	mg/kg	** Rayment & Lyons 2011 - 5A3a	<0.1	42.1
Chloride	%	** Rayment & Lyons 2011 - 5A3a	---	0.0042
Sulfate	mg/kg	** APHA 3120 ICPOES	<2	30
Sulfate	%	** APHA 3120 ICPOES	<0.0002	0.0030
Chloride:Sulfate Ratio	---	** Calculation	<0.1	1.4

Notes:

- NSCT (2009) texture: coarse and peats = sands to loamy sands; medium = clayey sand to light clays; fine = light medium to heavy clays.
- ** denotes NATA accreditation does not cover the performance of this service.
- .. denotes not requested, no data/information or no guidelines available.
- All services undertaken by EAL are covered by the EAL Laboratory Services Terms and Conditions (available on request or at scu.edu.au/eal).
- Analysis conducted between sample arrival date and reporting date.
- This report is not to be reproduced except in full.
- Results only relate to the item tested.
- Methods from Rayment and Lyons, 2011. Soil Chemical Methods - Australasia. CSIRO Publishing, Collingwood.
- All analysis is on a dry weight (DW) basis - samples were dried at 60 °C for 48 h prior to crushing and analysis.
- For conductivity 1 dS/m = 1 mS/cm = 1000 µS/cm.
- ppm = mg/kg dried sample

APPENDIX C

CSIRO Sheet BTF 18

Foundation Maintenance and Footing Performance: A Homeowner's Guide



PUBLISHING

BTF 18-2011
replaces
Information
Sheet 10/91

Buildings can and often do move. This movement can be up, down, lateral or rotational. The fundamental cause of movement in buildings can usually be related to one or more problems in the foundation soil. It is important for the homeowner to identify the soil type in order to ascertain the measures that should be put in place in order to ensure that problems in the foundation soil can be prevented, thus protecting against building movement.

This Building Technology File is designed to identify causes of soil-related building movement, and to suggest methods of prevention of resultant cracking in buildings.

Soil Types

The types of soils usually present under the topsoil in land zoned for residential buildings can be split into two approximate groups – granular and clay. Quite often, foundation soil is a mixture of both types. The general problems associated with soils having granular content are usually caused by erosion. Clay soils are subject to saturation and swell/shrink problems.

Classifications for a given area can generally be obtained by application to the local authority, but these are sometimes unreliable and if there is doubt, a geotechnical report should be commissioned. As most buildings suffering movement problems are founded on clay soils, there is an emphasis on classification of soils according to the amount of swell and shrinkage they experience with variations of water content. The table below is Table 2.1 from AS 2870-2011, the Residential Slab and Footing Code.

Causes of Movement

Settlement due to construction

There are two types of settlement that occur as a result of construction:

- Immediate settlement occurs when a building is first placed on its foundation soil, as a result of compaction of the soil under the weight of the structure. The cohesive quality of clay soil mitigates against this, but granular (particularly sandy) soil is susceptible.
- Consolidation settlement is a feature of clay soil and may take place because of the expulsion of moisture from the soil or because of the soil's lack of resistance to local compressive or shear stresses. This will usually take place during the first few months after construction, but has been known to take many years in exceptional cases.

These problems are the province of the builder and should be taken into consideration as part of the preparation of the site for construction. Building Technology File 19 (BTF 19) deals with these problems.

Erosion

All soils are prone to erosion, but sandy soil is particularly susceptible to being washed away. Even clay with a sand component of say 10% or more can suffer from erosion.

Saturation

This is particularly a problem in clay soils. Saturation creates a bog-like suspension of the soil that causes it to lose virtually all of its bearing capacity. To a lesser degree, sand is affected by saturation because saturated sand may undergo a reduction in volume, particularly imported sand fill for bedding and blinding layers. However, this usually occurs as immediate settlement and should normally be the province of the builder.

Seasonal swelling and shrinkage of soil

All clays react to the presence of water by slowly absorbing it, making the soil increase in volume (see table below). The degree of increase varies considerably between different clays, as does the degree of decrease during the subsequent drying out caused by fair weather periods. Because of the low absorption and expulsion rate, this phenomenon will not usually be noticeable unless there are prolonged rainy or dry periods, usually of weeks or months, depending on the land and soil characteristics.

The swelling of soil creates an upward force on the footings of the building, and shrinkage creates subsidence that takes away the support needed by the footing to retain equilibrium.

Shear failure

This phenomenon occurs when the foundation soil does not have sufficient strength to support the weight of the footing. There are two major post-construction causes:

- Significant load increase.
- Reduction of lateral support of the soil under the footing due to erosion or excavation.

In clay soil, shear failure can be caused by saturation of the soil adjacent to or under the footing.

GENERAL DEFINITIONS OF SITE CLASSES

Class	Foundation
A	Most sand and rock sites with little or no ground movement from moisture changes
S	Slightly reactive clay sites, which may experience only slight ground movement from moisture changes
M	Moderately reactive clay or silt sites, which may experience moderate ground movement from moisture changes
H1	Highly reactive clay sites, which may experience high ground movement from moisture changes
H2	Highly reactive clay sites, which may experience very high ground movement from moisture changes
E	Extremely reactive sites, which may experience extreme ground movement from moisture changes

Notes

1. Where controlled fill has been used, the site may be classified A to E according to the type of fill used.
2. Filled sites. Class P is used for sites which include soft fills, such as clay or silt or loose sands; landslide; mine subsidence; collapsing soils; soil subject to erosion; reactive sites subject to abnormal moisture conditions or sites which cannot be classified otherwise.
3. Where deep-seated moisture changes exist on sites at depths of 3 m or greater, further classification is needed for Classes M to E (M-D, H1-D, H2-D and E-D).

Tree root growth

Trees and shrubs that are allowed to grow in the vicinity of footings can cause foundation soil movement in two ways:

- Roots that grow under footings may increase in cross-sectional size, exerting upward pressure on footings.
- Roots in the vicinity of footings will absorb much of the moisture in the foundation soil, causing shrinkage or subsidence.

Unevenness of Movement

The types of ground movement described above usually occur unevenly throughout the building's foundation soil. Settlement due to construction tends to be uneven because of:

- Differing compaction of foundation soil prior to construction.
- Differing moisture content of foundation soil prior to construction.

Movement due to non-construction causes is usually more uneven still. Erosion can undermine a footing that traverses the flow or can create the conditions for shear failure by eroding soil adjacent to a footing that runs in the same direction as the flow.

Saturation of clay foundation soil may occur where subfloor walls create a dam that makes water pond. It can also occur wherever there is a source of water near footings in clay soil. This leads to a severe reduction in the strength of the soil which may create local shear failure.

Seasonal swelling and shrinkage of clay soil affects the perimeter of the building first, then gradually spreads to the interior. The swelling process will usually begin at the uphill extreme of the building, or on the weather side where the land is flat. Swelling gradually reaches the interior soil as absorption continues. Shrinkage usually begins where the sun's heat is greatest.

Effects of Uneven Soil Movement on Structures

Erosion and saturation

Erosion removes the support from under footings, tending to create subsidence of the part of the structure under which it occurs. Brickwork walls will resist the stress created by this removal of support by bridging the gap or cantilevering until the bricks or the mortar bedding fail. Older masonry has little resistance. Evidence of failure varies according to circumstances and symptoms may include:

- Step cracking in the mortar beds in the body of the wall or above/below openings such as doors or windows.
- Vertical cracking in the bricks (usually but not necessarily in line with the vertical beds or perpend).

Isolated piers affected by erosion or saturation of foundations will eventually lose contact with the bearers they support and may tilt or fall over. The floors that have lost this support will become bouncy, sometimes rattling ornaments etc.

Seasonal swelling/shrinkage in clay


Swelling foundation soil due to rainy periods first lifts the most exposed extremities of the footing system, then the remainder of the perimeter footings while gradually permeating inside the building footprint to lift internal footings. This swelling first tends to create a dish effect, because the external footings are pushed higher than the internal ones.

The first noticeable symptom may be that the floor appears slightly dished. This is often accompanied by some doors binding on the floor or the door head, together with some cracking of cornice mitres. In buildings with timber flooring supported by bearers and joists, the floor can be bouncy. Externally there may be visible dishing of the hip or ridge lines.

As the moisture absorption process completes its journey to the innermost areas of the building, the internal footings will rise. If the spread of moisture is roughly even, it may be that the symptoms will temporarily disappear, but it is more likely that swelling will be uneven, creating a difference rather than a disappearance in symptoms. In buildings with timber flooring supported by bearers and joists, the isolated piers will rise more easily than the strip footings or piers under walls, creating noticeable doming of flooring.

As the weather pattern changes and the soil begins to dry out, the external footings will be first affected, beginning with the locations where the sun's effect is strongest. This has the effect of lowering the

Trees can cause shrinkage and damage



external footings. The doming is accentuated and cracking reduces or disappears where it occurred because of dishing, but other cracks open up. The roof lines may become convex.

Doming and dishing are also affected by weather in other ways. In areas where warm, wet summers and cooler dry winters prevail, water migration tends to be toward the interior and doming will be accentuated, whereas where summers are dry and winters are cold and wet, migration tends to be toward the exterior and the underlying propensity is toward dishing.

Movement caused by tree roots

In general, growing roots will exert an upward pressure on footings, whereas soil subject to drying because of tree or shrub roots will tend to remove support from under footings by inducing shrinkage.

Complications caused by the structure itself

Most forces that the soil causes to be exerted on structures are vertical – i.e. either up or down. However, because these forces are seldom spread evenly around the footings, and because the building resists uneven movement because of its rigidity, forces are exerted from one part of the building to another. The net result of all these forces is usually rotational. This resultant force often complicates the diagnosis because the visible symptoms do not simply reflect the original cause. A common symptom is binding of doors on the vertical member of the frame.

Effects on full masonry structures

Brickwork will resist cracking where it can. It will attempt to span areas that lose support because of subsided foundations or raised points. It is therefore usual to see cracking at weak points, such as openings for windows or doors.

In the event of construction settlement, cracking will usually remain unchanged after the process of settlement has ceased.

With local shear or erosion, cracking will usually continue to develop until the original cause has been remedied, or until the subsidence has completely neutralised the affected portion of footing and the structure has stabilised on other footings that remain effective.

In the case of swell/shrink effects, the brickwork will in some cases return to its original position after completion of a cycle, however it is more likely that the rotational effect will not be exactly reversed, and it is also usual that brickwork will settle in its new position and will resist the forces trying to return it to its original position. This means that in a case where swelling takes place after construction and cracking occurs, the cracking is likely to at least partly remain after the shrink segment of the cycle is complete. Thus, each time the cycle is repeated, the likelihood is that the cracking will become wider until the sections of brickwork become virtually independent.

With repeated cycles, once the cracking is established, if there is no other complication, it is normal for the incidence of cracking to stabilise, as the building has the articulation it needs to cope with the problem. This is by no means always the case, however, and monitoring of cracks in walls and floors should always be treated seriously.

Upheaval caused by growth of tree roots under footings is not a simple vertical shear stress. There is a tendency for the root to also exert lateral forces that attempt to separate sections of brickwork after initial cracking has occurred.

The normal structural arrangement is that the inner leaf of brickwork in the external walls and at least some of the internal walls (depending on the roof type) comprise the load-bearing structure on which any upper floors, ceilings and the roof are supported. In these cases, it is internally visible cracking that should be the main focus of attention, however there are a few examples of dwellings whose external leaf of masonry plays some supporting role, so this should be checked if there is any doubt. In any case, externally visible cracking is important as a guide to stresses on the structure generally, and it should also be remembered that the external walls must be capable of supporting themselves.

Effects on framed structures

Timber or steel framed buildings are less likely to exhibit cracking due to swell/shrink than masonry buildings because of their flexibility. Also, the doming/dishing effects tend to be lower because of the lighter weight of walls. The main risks to framed buildings are encountered because of the isolated pier footings used under walls. Where erosion or saturation causes a footing to fall away, this can double the span which a wall must bridge. This additional stress can create cracking in wall linings, particularly where there is a weak point in the structure caused by a door or window opening. It is, however, unlikely that framed structures will be so stressed as to suffer serious damage without first exhibiting some or all of the above symptoms for a considerable period. The same warning period should apply in the case of upheaval. It should be noted, however, that where framed buildings are supported by strip footings there is only one leaf of brickwork and therefore the externally visible walls are the supporting structure for the building. In this case, the subfloor masonry walls can be expected to behave as full brickwork walls.

Effects on brick veneer structures

Because the load-bearing structure of a brick veneer building is the frame that makes up the interior leaf of the external walls plus perhaps the internal walls, depending on the type of roof, the building can be expected to behave as a framed structure, except that the external masonry will behave in a similar way to the external leaf of a full masonry structure.

Water Service and Drainage

Where a water service pipe, a sewer or stormwater drainage pipe is in the vicinity of a building, a water leak can cause erosion, swelling or saturation of susceptible soil. Even a minuscule leak can be enough to saturate a clay foundation. A leaking tap near a building can have the same effect. In addition, trenches containing pipes can become watercourses even though backfilled, particularly where broken rubble is used as fill. Water that runs along these trenches can be responsible for serious erosion, interstrata seepage into subfloor areas and saturation.

Pipe leakage and trench water flows also encourage tree and shrub roots to the source of water, complicating and exacerbating the problem. Poor roof plumbing can result in large volumes of rainwater being concentrated in a small area of soil:

- Incorrect falls in roof guttering may result in overflows, as may gutters blocked with leaves etc.

- Corroded guttering or downpipes can spill water to ground.
- Downpipes not positively connected to a proper stormwater collection system will direct a concentration of water to soil that is directly adjacent to footings, sometimes causing large-scale problems such as erosion, saturation and migration of water under the building.

Seriousness of Cracking

In general, most cracking found in masonry walls is a cosmetic nuisance only and can be kept in repair or even ignored. The table below is a reproduction of Table C1 of AS 2870-2011.

AS 2870-2011 also publishes figures relating to cracking in concrete floors, however because wall cracking will usually reach the critical point significantly earlier than cracking in slabs, this table is not reproduced here.

Prevention/Cure

Plumbing

Where building movement is caused by water service, roof plumbing, sewer or stormwater failure, the remedy is to repair the problem. It is prudent, however, to consider also rerouting pipes away from the building where possible, and relocating taps to positions where any leakage will not direct water to the building vicinity. Even where gully traps are present, there is sometimes sufficient spill to create erosion or saturation, particularly in modern installations using smaller diameter PVC fixtures. Indeed, some gully traps are not situated directly under the taps that are installed to charge them, with the result that water from the tap may enter the backfilled trench that houses the sewer piping. If the trench has been poorly backfilled, the water will either pond or flow along the bottom of the trench. As these trenches usually run alongside the footings and can be at a similar depth, it is not hard to see how any water that is thus directed into a trench can easily affect the foundation's ability to support footings or even gain entry to the subfloor area.

Ground drainage

In all soils there is the capacity for water to travel on the surface and below it. Surface water flows can be established by inspection during and after heavy or prolonged rain. If necessary, a grated drain system connected to the stormwater collection system is usually an easy solution.

It is, however, sometimes necessary when attempting to prevent water migration that testing be carried out to establish watertable height and subsoil water flows. This subject is referred to in BTF 19 and may properly be regarded as an area for an expert consultant.


Protection of the building perimeter

It is essential to remember that the soil that affects footings extends well beyond the actual building line. Watering of garden plants, shrubs and trees causes some of the most serious water problems.

For this reason, particularly where problems exist or are likely to occur, it is recommended that an apron of paving be installed around as much of the building perimeter as necessary. This paving should

CLASSIFICATION OF DAMAGE WITH REFERENCE TO WALLS		
Description of typical damage and required repair	Approximate crack width limit (see Note 3)	Damage category
Hairline cracks	<0.1 mm	0
Fine cracks which do not need repair	<1 mm	1
Cracks noticeable but easily filled. Doors and windows stick slightly.	<5 mm	2
Cracks can be repaired and possibly a small amount of wall will need to be replaced. Doors and windows stick. Service pipes can fracture. Weathertightness often impaired.	5–15 mm (or a number of cracks 3 mm or more in one group)	3
Extensive repair work involving breaking-out and replacing sections of walls, especially over doors and windows. Window and door frames distort. Walls lean or bulge noticeably, some loss of bearing in beams. Service pipes disrupted.	15–25 mm but also depends on number of cracks	4

Gardens for a reactive site



extend outwards a minimum of 900 mm (more in highly reactive soil) and should have a minimum fall away from the building of 1:60. The finished paving should be no less than 100 mm below brick vent bases.

It is prudent to relocate drainage pipes away from this paving, if possible, to avoid complications from future leakage. If this is not practical, earthenware pipes should be replaced by PVC and backfilling should be of the same soil type as the surrounding soil and compacted to the same density.

Except in areas where freezing of water is an issue, it is wise to remove taps in the building area and relocate them well away from the building – preferably not uphill from it (see BTF 19).

It may be desirable to install a grated drain at the outside edge of the paving on the uphill side of the building. If subsoil drainage is needed this can be installed under the surface drain.

Condensation

In buildings with a subfloor void such as where bearers and joists support flooring, insufficient ventilation creates ideal conditions for condensation, particularly where there is little clearance between the floor and the ground. Condensation adds to the moisture already present in the subfloor and significantly slows the process of drying out. Installation of an adequate subfloor ventilation system, either natural or mechanical, is desirable.

Warning: Although this Building Technology File deals with cracking in buildings, it should be said that subfloor moisture can result in the development of other problems, notably:

- Water that is transmitted into masonry, metal or timber building elements causes damage and/or decay to those elements.
- High subfloor humidity and moisture content create an ideal environment for various pests, including termites and spiders.
- Where high moisture levels are transmitted to the flooring and walls, an increase in the dust mite count can ensue within the living areas. Dust mites, as well as dampness in general, can be a health hazard to inhabitants, particularly those who are abnormally susceptible to respiratory ailments.

The garden

The ideal vegetation layout is to have lawn or plants that require only light watering immediately adjacent to the drainage or paving edge, then more demanding plants, shrubs and trees spread out in that order.

Overwatering due to misuse of automatic watering systems is a common cause of saturation and water migration under footings. If it is necessary to use these systems, it is important to remove garden beds to a completely safe distance from buildings.

Existing trees

Where a tree is causing a problem of soil drying or there is the existence or threat of upheaval of footings, if the offending roots are subsidiary and their removal will not significantly damage the tree, they should be severed and a concrete or metal barrier placed vertically in the soil to prevent future root growth in the direction of the building. If it is not possible to remove the relevant roots without damage to the tree, an application to remove the tree should be made to the local authority. A prudent plan is to transplant likely offenders before they become a problem.

Information on trees, plants and shrubs

State departments overseeing agriculture can give information regarding root patterns, volume of water needed and safe distance from buildings of most species. Botanic gardens are also sources of information. For information on plant roots and drains, see Building Technology File 17.

Excavation

Excavation around footings must be properly engineered. Soil supporting footings can only be safely excavated at an angle that allows the soil under the footing to remain stable. This angle is called the angle of repose (or friction) and varies significantly between soil types and conditions. Removal of soil within the angle of repose will cause subsidence.

Remediation

Where erosion has occurred that has washed away soil adjacent to footings, soil of the same classification should be introduced and compacted to the same density. Where footings have been undermined, augmentation or other specialist work may be required. Remediation of footings and foundations is generally the realm of a specialist consultant.

Where isolated footings rise and fall because of swell/shrink effect, the homeowner may be tempted to alleviate floor bounce by filling the gap that has appeared between the bearer and the pier with blocking. The danger here is that when the next swell segment of the cycle occurs, the extra blocking will push the floor up into an accentuated dome and may also cause local shear failure in the soil. If it is necessary to use blocking, it should be by a pair of fine wedges and monitoring should be carried out fortnightly.

This BTF was prepared by John Lewer FAIB, MIAMA, Partner, Construction Diagnosis.

The information in this and other issues in the series was derived from various sources and was believed to be correct when published.

The information is advisory. It is provided in good faith and not claimed to be an exhaustive treatment of the relevant subject.

Further professional advice needs to be obtained before taking any action based on the information provided.

Distributed by

CSIRO PUBLISHING PO Box 1139, Collingwood 3066, Australia

Tel (03) 9662 7666 Fax (03) 9662 7555 www.publish.csiro.au

Email: publishing.sales@csiro.au

© CSIRO 2003. Unauthorised copying of this Building Technology File is prohibited